STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

JAN 2 8 2005

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Gener	ral Information
	1.	Report Time Period: From (mo./yr.)1_1_04 To (mo./yr.)12_31_04
	2.	DOGM File Number (Mine No) S1 5 / 00 /77
	3.	Mine Name: BLUE CASTLE
	4.	Mineral(s) Mined (or permitted to mine): Noble Metals
	5.	Type of mine
	6.	Legal Description (Location of Lands Affected):
		E 1/4, NE 1/4, SE 1/4, Section 29, Township 16S, Range 14E
		1/4,1/4,1/4, Section, Township, Range
		1/4,1/4,1/4, Section, Township, Range
7.	Name	of Operator or Company: GOLDTERRA, INC.
	8.	Permanent Street Address: 4088 East Airport Rd - PO Box 783
		City, State, Zip: Price, Utah 84501
		Phone: (435)636-8888 Fax: (435)637-3888
	9.	Company Representative (or designated operator):
		Name: Dan Sheppard
		Title: President
		Business Address: 4088 East Airport Rd - P.O. Box 783
		City, State, Zip: Price, Utah 84501
		Phone: (435)636-8888 Fax: (435)637-3888
		Please check if any of the above information has changed since previous year.
II.	Mining	and Reclamation
	1.	Was there any mine related activity during the past year? Yes ☒ No ☐
	2.	If no - what was the last year of activity?
	3.	If yes - how much ore or mineral was mined? Approximately 500 Tons.
eview	ed 2	18/05 PBB Based on inspection, I her any material was mined
estion	shell	her any material was mined

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.			
	Approximately 500 Tons of material was trucked to our			
	pilot mill located at 4088 East Airport Road - Price,			
	Utah 84501			
5.	How much additional acreage was disturbed during the past year? Less than 1 Acre			
6.	How much acreage was reclaimed during the past year? None			
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.			
	N/A			
8.	What is the total disturbed acreage of entire project at years end? Less than 1 Acr			
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year. Plan to excavate Material and truck to the Pilot Mill			
	located at 4088 East Airport Road - Price, Utah, at a rate			
	of 50 tons per day.			
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .			
III. <u>Additional I</u>	Information - R647-4-121.2 and .3			
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.			
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.			
IV. <u>Signature</u>	Requirement			
I herek	by certify that the foregoing is true and correct.			
	Name (Typed or Print): Dan_Sheppard			
	Title of Operator: President			
	Signature of Operator:			
	Date: January 27, 2005			

jb
o:\forms\reports\MR-AR